


419 Main Street—Emergency Repair—Brick Infill of Window Opening due to Unforeseen Structural Issue

Modification to a COA that was approved in August 2019. At that time, window was to be restored.



Prior Interior Condition - Exposed structural issue above window that required immediate attention

Current Condition - Brick infill solution of exterior window completed in late March 2020

Prior Exterior Condition - Boarded-up window



West Face –facing alley



April 16, 2020